




GRANDT LINE PRODUCTS




[home](#) | [Model Railroad](#) | [Dollhouse Miniatures](#) | [Architectural](#)
[Ordering Info](#) | [Customer Support](#) | [Price List](#) | [Business and Foreign Customers](#)

How to create grab-irons using #1 NBW: [click here D](#)

Nuts and Bolts: Measurements in inches are across the flat of the nut						
No.		Scale	Description	Meas. (inches)	Qty	Price
1		1/4"	1 1/4" SQUARE NUT, BOLT, WASHER	.026"	175	3.00
63		1/4"	1/2" SQUARE NUT, BOLT, WASHER	.010"	175	3.00
9		1/4"	1" SQUARE NUT, BOLT	.021"	175	3.00
82		1/4"	2 1/2" SQUARE NUT-NO WASHER	.052"	100	3.00
15		1/4"	1 1/4" HEX NUT, BOLT	.026"	175	3.00
127		1/4"	1 1/2" HEX NUT, BOLT-NO WASHER	.031"	100	3.00
128		1/4"	2 1/2" HEX NUT, BOLT-NO WASHER	.060"	100	3.00
18		1/4"	2 1/2" NUT ON RECTANGULAR WASHER	.052"	20	3.00
5094		HO	2 1/2" SQUARE NUT ON CARTER BROS. ELLIPTICAL WASHER	.029"	100	3.00
20		1/4"	2 1/2" SQUARE NUT ON CARTER BROS. ELLIPTICAL WASHER	.052"	20	3.00
44		1/4"	2 1/8" SQUARE NUT, 5" RIBBED WASHER	.044"	20	3.00
62		1/4"	7/8" SQUARE NUT, BOLT, CAST IRON WASHER	.018"	175	3.00
23		1/4"	1 1/2" SQUARE NUT, BOLT, CAST IRON WASHERS	.031"	100	3.00
16		1/4"	2 1/2" SQUARE NUT, BOLT, CAST IRON WASHER	.052"	50	3.00
80		1/4"	2 1/2" SQUARE NUT ON 6" SQUARE WASHER	.052"	50	3.00
81		1/4"	2 1/2" HEX NUT ON 6" SQUARE WASHER	.052"	50	3.00
5066		HO	1 1/4" NUT, 3" MALLEABLE WASHER	.014"	175	3.00
93		1/4"	1 1/4" NUT, 3" MALLEABLE WASHER	.026"	100	3.00
100		1/4"	7/8" NUT, 1 3/8" STEEL WASHER, 1/2" BOLT	.018"	175	3.00
101		1/4"	1 1/6" NUT, 1 3/4" STEEL WASHERS, 5/8" BOLT	.022"	175	3.00
98		1/4"	1 1/2" NUT, 2" STEEL WASHER, 3/4" BOLT	.026"	175	3.00
8		1/4"	1 1/4" SQUARE NUT, BOLT (1/2 of the casting sprue has the nut/bolt with a washer, 1/2 has no washer)	.026"	175	3.00
99		1/4"	1 5/8" NUT, 2 1/2" STEEL	.034"	100	3.00

			WASHER, 1" BOLT			
139		1/4"	1 1/2" NUT WITH 4" CAST IRON WASHER-CORED FOR .020" WIRE	.031"	80	3.00
162		1/4"	WING NUT ASSORTMENT 4 sizes: lg (9 ea), med (9ea), small (12 ea), xsmall (12 ea)	lg: .175" med: .135" sm: .100" xsm: .060"	3 SETS	3.00
163		1/4"	STAR NUT, BOLT, WASHERS	.075"	100	3.00
3911		1/2"	HEX NUT ON SQUARE, RIBBED CAST IRON WASHER:	.115" across the flat of the nut	24	3.60
3912		1/2"	HEX NUT ON ROUND, CAST IRON WASHER	.105" across the flat of the nut	30	3.60

Turnbuckles: Measurements are length of turnbuckle, followed by width					
No.	Photo	Scale	Description	Meas. (inches)	
54		1/4"	SCALE TURNBUCKLES-cored for .025" wire	.200, .060	
81054			same in brass		
4019		S	TURNBUCKLES	.180, .050	
4042			same in brass		
5039		HO	SCALE TURNBUCKLES	.100, .040	
86039			same, in brass		

Lift Rings/Eyebolts and Rivets: Can be used in all scales					
No.		Description	Meas. (inches)	Qty	Price
108		LIFT RINGS AND EYEBOLTS	center mount: .07"/.065"/.035" DIA. side mount: .065"/.035" DIA.	ASST	3.00
152		RIVETS- CONICAL HEAD	.032" DIA.	175	3.00
155			.043" DIA.	175	3.00
157			.063" DIA.	100	3.00
153		RIVETS- ROUND HEAD	.032" DIA.	175	3.00
154			.043" DIA.	175	3.00
156			.063" DIA.	100	3.00

Send mail to pnish@pacbell.net with questions or comments about this web site.
Last modified: 10/13/10